

LXi Replacement Parts List - Fire Pump Controllers

Replacement Parts Fire Pump Controllers · November 2008, Replaces May 2008



"D" Version - Controller with A-B Circuit Breakers and Contactors			
Part No.	Description	List Price	Material Price Group
HC90215701	SPC Board (top)	\$ 759	E9
HC90220701	ICD Board (middle)	\$ 387	E9
HC90210701	MSTM Board (bottom)	\$ 478	E9
HC90214301	LCD Keypad	\$ 573	E9
HC90213701	LED Board	\$ 231	E9
HCPS3031	Power Supply	\$ 135	E9
HC57529011	Pressure Transducer	\$ 265	E9
HC31658003	12VDC Relay	\$ 71	FE
HCCN4303	Cat 5 Cable 2 meter	\$ 30	E9
HC90206015	Cat 5 Cable 1 foot	\$ 13	E9
HC57418399	Phase Loss Monitor 480 VAC	\$ 254	E9
HC57418398	Phase Loss Monitor 208-240 VAC	\$ 254	E9
HC49225101	Soft Start Control Board	\$ 1,093	E9

"C" Version - Controllers with GE Circuit Breakers & Contactors			
Part No.	Description	List Price	Material Price Group
HC90215701	SPC Board (top)	\$ 759	E9
HC90214301	LCD Keypad	\$ 573	E9
HC90206016	Jumper Assy for LCD USB to Phoenix Connectors	N/C with a Keypad Purchase	E9
HC90213701	LED Board	\$ 231	E9
HCPS3031	Power Supply	\$ 135	E9
HC57529011	Pressure Transducer	\$ 265	E9
HC31658003	12VDC Relay	\$ 71	E9
HCCN4303	Cat 5 Cable 2 meter	\$ 30	E9
HC90206015	Cat 5 Cable 1 foot	\$ 13	E9
HC57418399	Phase Loss Monitor 480 VAC	\$ 254	E9
HC57418398	Phase Loss Monitor 208-240 VAC	\$ 254	E9
HC49225101	Soft Start Control Board	\$ 1093	E9
HC90202312	Complete Control Panel	\$ 2800	E9
Consult Factory	Panel Replacement (If ICD board needed)	Consult Factory	E9
HC49224201	Current Shunt Trip Module	\$ 386	E9